ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W1246, W1911, W1244, W1959, W1250, W1949, W1252, W

Street Name
NA, Ambedkar Colony, Mission Rd, 7th Crs, 2nd Crs

Significant Landmark
Chanakaya Layout

Segment No.
6/C-W1246/S083653

Total Length (m)
389.83

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	82.89	77.620307	13.040148	77.620437	13.040887	W1903	RI-A06
2	124.74	77.620783	13.039792	77.621073	13.040883	W1911	RI-A06
3	182.20	77.622163	13.039340	77.622626	13.040924	W1260	RI-A06

Work Details

History of Road / Lane / Circles

Name of the Work
Improvement to Road and Drain at Chanakaya Layout in ward no 6 Byatarayanapura Sub Division yelahanka zone

Sanctioned Estimated Amount (Rs.)
3000000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvement to Road and Drain at Chanakaya Layout in ward no 6 Byatarayanapura Sub Division yelahanka zone

Job No. / Work Code
JOB CODE 006-15-000046

Work Order No.
BBMP/EE/BTP/WO/58/2016-17

Work Order Date
23/06/2016

Period of Extention
90 DAYS

Defect Liability Period From
23/06/2016

Defect Liability Period To
22/06/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
K.LAKSHMI NARAYANA REDDY

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.
9740402579

E-Mail ID

Field Inspection Details

Number of Trees	Any Other Information	Name
0		KRISHNAPPA

Date of Inspection	Remarks
04/11/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1246, W1911, W1244, W1959,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	04/11/2016	04/12/2016	COMPLETED
SE	VASU K M	04/11/2016	04/12/2016	COMPLETED
EE	YARAPPA REDDY	04/11/2016	04/12/2016	COMPLETED
AEE	J N LOKESH	04/11/2016	04/12/2016	COMPLETED
AE	KRISHNAPPA	04/11/2016	04/12/2016	COMPLETED
AE	KRISHNAPPA	04/11/2016	04/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1246, W1911, W1244, W1959,